


NOTES:

- 1 5874PBF (ITEM 2) INCLUDES VRK5874 CARTRIDGE ASSEMBLY (ITEM 3) AND PBA6 FLANGED PUSH BUTTON (ITEM 4).

ITEM	DESCRIPTION	1001MS	1001HPSMS
1	STRAINER	6463	6463PCP
2	BUTTON, PUSH, FLANGED, PCP, W/ VALVE	5874PBF	5874PBF
3	VALVE REPAIR KIT	VRK5874	VRK5874
4	PUSH BUTTON ASSY	PBA6	PBA6
5	BUBBLER HEAD & INSERT	5705	5705
6	BOTTOM PLATE	PBM1000	PBM1000
7	BACK PANEL	BP6	BP6HPS
8	MOUNTING FRAME	MTGFR.DF1	MTGFR.DF1
9	ACCESS PANEL	6606	6606HPS
* 10	INSERT, LAMINAR FLOW	0002850230	0002850230
* 11	DRIVER, NOZZLE .25 HEX	0002082253	0002082253

* DENOTES OPTIONAL PART.



PARTS BREAKDOWN

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.

		1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWS.CO.COM WEBSITE: WWW.HAWS.CO.COM	
		MODEL(S) 1001MS/1001HPSMS DRINKING FOUNTAIN	
ECN NO. ECN: 5124	REVISED PER DATE 08/02/99	BY CHKD VWC	PART NUMBER 0002076510
DRAWN PM	DATE 07/06/17	APPROVED FV	REVISION 9
SCALE: 1:5		DRAWING TYPE: PARTS BREAKDOWN	SIZE: A SHEET 1 OF 1